

Stryker's Total Joint Implants

Magnetic Resonance Imaging Information

1. Introduction

This document is intended to provide Magnetic Resonance Imaging (MRI) information regarding Stryker orthopaedic' implants. With the growing use of MRI scanners to more accurately assess patients, the need to understand how the MRI scanner interacts with passive metallic implants has become ever more necessary. Stryker has performed testing according to ASTM standards to determine the level of safety of their products.

The MR environment includes the static magnetic field (1.5 & 3.0 Tesla most common), the imaging gradient field (in the range of kHz), and the radio frequency (RF) field (1.5-T/64MHz & 3.0-T/128Mhz). Each of these fields interacts with implants in different ways, producing medical device concerns that may be potentially detrimental to an implant recipient. These concerns include: magnetic field interactions (including magnetically induced displacement and rotational force) on the implant, MR induced image artifacts, and RF induced currents resulting in heating.

2. Magnetic Field Interactions

Stryker orthopaedic' implant metallic components may include the following non- ferromagnetic materials: Commercially Pure Titanium (CP-Ti), Titanium Alloys (Ti- 6Al-4V & TMZF), Cobalt Chrome (CoCr), and specific Stainless Steel grades (REX 734). Testing performed on non-ferromagnetic devices included in Appendix I concluded that magnetic field interactions (including magnetically induced displacement and torque) were acceptable.

3. RF-Induced Heating Interactions

The RF field of the MR can interact with a metallic component's geometry causing concern of induced heating. In particular, elongated features (i.e., distal shaft of the femoral stem or bone screws) can form a resonance antenna and result in internal heating. Stryker orthopaedic' components listed in Appendix I were evaluated to determine the extent of induced heating and temperature rises were found to be acceptable.

4. Imaging Artifacts

The static field of an MR system can cause image distortion and signal loss artifacts. These artifacts do not compromise patient safety and therefore are not considered a performance risk. Testing was carried out to characterize these artifacts and determine to what extent these artifacts will affect image quality.

MR Test Recommendations:

The scope of this document covers devices included in Appendix I. These devices are MR Conditional according to the terminology specified in ASTM F2503, Standard Practice for Marketing Medical Devices and Other Items for Safety in the Magnetic Resonance Environment. Non-clinical testing has demonstrated that the devices included in Appendix I are MR Conditional. A patient with any of these devices can be safely scanned in an MR system meeting the following conditions:

- Static magnetic field of 1.5-Telsa and 3.0-Tesla, only
- Maximum spatial gradient magnetic field of 2,310 gauss/cm (23 T/m)
- Maximum MR system reported, whole body averaged specific absorption rate (SAR) of 2 W/kg for 15 minutes of scanning in the Normal Operating Mode of operation for the MR system.
- Evaluation was performed using a quadrature body coil only

Under the scan conditions defined above, devices covered in Appendix I are expected to produce a temperature rise of less than 4.1 °C after 15 minutes of continuous scanning.

In non-clinical testing, the image artifact caused by the device extends approximately 84 mm from the device when imaged with a gradient echo pulse sequence using a 3.0 T/128 MHz MRI system.

Unless listed in Appendix I, other total joint products have not been evaluated for safety and compatibility in the MR environment. These products have not been tested for heating, migration, or image artifact in the MR environment. The safety of these products in the MR environment is unknown. Scanning a patient with a total joint device not listed in Appendix I may result in patient injury.

Surgeons should warn patients with metallic implants of the potential risks of undergoing a MRI scan. The electromagnetic field created by an MRI scanner can interact with the metallic implant, resulting in displacement of the implant, heating of the tissue near the implant, implant damage or malfunction, or other undesirable effects. In addition, the presence of a metallic implant can produce an image artifact that may appear as a void region or geometric distortion of the true image. If the image artifact is near the area of interest, it may make the MRI scan uninformative or may lead to inaccurate clinical diagnosis or treatment.

Appendix I

Product Name	Catalog Numbers
Trident II Tritanium Solidback Acetabular Shell	700-04-42A
	700-04-44B
	700-04-46C
	700-04-48D
	700-04-50D
	700-04-52E
	700-04-54E
	700-04-56F
	700-04-58F
	700-04-60G
	700-04-62G
	700-04-64H
	700-04-66H
Trident II Tritanium Clusterhole Acetabular Shell	702-04-42A
	702-04-44B
	702-04-46C
	702-04-48D
	702-04-50D
	702-04-52E
	702-04-54E
	702-04-56F
	702-04-58F
	702-04-60G
	702-04-62G
	702-04-64H
	702-04-66H
Trident II Tritanium Multihole Acetabular Shell	709-04-42A
	709-04-44B
	709-04-46C
	709-04-48D
	709-04-50D
	709-04-52E
	709-04-54E
	709-04-56F
	709-04-58F
	709-04-60G
	709-04-62G
	709-04-64H
	709-04-66H

	700.04.001
	709-04-68I
	709-04-70I
	709-04-72J
Trident II PSL Clusterhole HA Acetabular Shell	742-11-42A
	742-11-44B
	742-11-46C
	742-11-48D
	742-11-50D
	742-11-52E
	742-11-54E
	742-11-56F
	742-11-58F
	742-11-60G
	742-11-62G
	742-11-64H
	742-11-66H
	702-11-42A
	702-11-44B
	702-11-46C
Trident II Clusterhole HA Acetabular Shell	702-11-48D
	702-11-50D
	702-11-52E
	702-11-54E
	702-11-56F
	702-11-58F
	702-11-60G
	702-11-62G
	702-11-64H
	702-11-66H
6.5mm Low Profile Hex Screw	7030-6515
	7030-6520
	7030-6525
	7030-6530
	7030-6535
	7030-6540
	7030-6545
	7030-6550
	7030-6555
Hay Dome Hale Dive	7030-6560
Hex Dome Hole Plug	7060-0000

GSNPS-BUL-9_13072 (also referenced as GSNPS-BULL-9_13072)

Orthopaedics

The information contained in this document is intended for healthcare professionals only.

A surgeon must always rely on his or her own professional clinical judgment when deciding whether to use a particular product when treating a particular patient. Stryker does not dispense medical advice and recommends that surgeons be trained in the use of any particular product before using it in surgery.

The information presented is intended to demonstrate the breadth of Stryker's product offerings. A surgeon must always refer to the package insert, product label and/or instructions for use before using any of Stryker's products. The products depicted are CE marked according to the Medical Device Directive 93/42/EEC, unless otherwise indicated. Products may not be available in all markets because product availability is subject to the regulatory and/or medical practices in individual markets.

Please contact your sales representative if you have questions about the availability of products in your area.

Stryker Corporation or its divisions or other corporate affiliated entities own, use or have applied for the following trademarks or service marks: CuttingEdge, LFIT, MDM, Stryker, Stryker Orthopaedics, Trident, Tritanium, V40, X3. All other trademarks are trademarks of their respective owners or holders.